


PRAKTIKUM 3

Wiring :



UNO	LDR
VCC	VCC
GND	GND
A0	A0

Code :

```
void setup() {  
  pinMode(A0,INPUT);  
  Serial.begin(9600);  
}  
void loop() {  
  int sensor=analogRead(A0);  
  Serial.println(sensor);  
  delay(300);  
}
```

Tampilan Serial Monitor :

